

APPENDIX B

DIGITAL PHOTOGRAPHS

(Will be included in final CD deliverable.)



9965090



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: NW
Photo Name: 2017-09-27_IMG_1529.JPG
Date and Time: 9/27/2017 9:47:00 AM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Derrick Cobb
Witness: Steve Mason
Caption: Oily sludge/oily impacted soils.



Incident Name: Removal Action (b) (6)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: W

Photo Name: 2017-09-27_IMG_1530.JPG

Date and Time: 9/27/2017 9:50:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Derrick Cobb

Witness: Steve Mason

Caption: Loading dump truck with oily sludge and oily impacted soils for off-site disposal.



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: E
Photo Name: 2017-09-28_IMG_1534.JPG
Date and Time: 9/28/2017 11:30:00 AM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Derrick Cobb
Witness: Steve Mason
Caption: Oily sludge/oily impacted soils.



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: N
Photo Name: 2017-10-02_IMG_1537.JPG
Date and Time: 10/2/2017 8:03:00 AM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Derrick Cobb
Witness: Meagan Willis
Caption: Overview of excavation.



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: NW
Photo Name: 2017-10-03_IMG_0523.JPG
Date and Time: 10/3/2017 4:26:00 PM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Meagan Willis
Witness: Steve Mason
Caption: Backfilling of excavation



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: NW
Photo Name: 2017-10-10_IMG_0588.JPG
Date and Time: 10/10/2017 4:09:00 PM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Meagan Willis
Witness: Steve Mason
Caption: Completion of compaction and backfilling operations.



(b) (6)

A large rectangular area of the page is completely blacked out, indicating a full-page redaction of the photo report's content.

Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: SW
Photo Name: 2017-10-11_IMG_0596.JPG
Date and Time: 10/11/2017 8:42:00 AM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Meagan Willis
Witness: Steve Mason
Caption: Replanting of trees removed
during the removal operations.



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: SE
Photo Name: 2017-10-11_IMG_0601.JPG
Date and Time: 10/11/2017 11:12:00 AM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Meagan Willis
Witness: Steve Mason
Caption: Hydro-seeding of the excavated area.



Incident Name: Removal Action (b) (6)
Event Name: Wilcox Oil
Photo Type: Overview
Direction: N
Photo Name: 2017-10-11_IMG_0620.JPG
Date and Time: 10/11/2017 5:38:00 PM
Latitude: (b) (6)
Longitude: (b) (6)
Photographer: Meagan Willis
Witness: Steve Mason
Caption: Overview of final restored area.